

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments | Error Definition | Errors |
|---|------|-----|------|---|---|---------------------|----------|------------------|--------|
| 1 | BRS | L1 | 510 | (girder with deck) and connect\$ | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB | 2004/10/14 11:27 | | | 0 |
| 2 | BRS | L2 | 25 | (girder with deck) and connect\$ and fasten\$ and ((precast prefabricated) with deck) | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB | 2004/10/14 11:36 | | | 0 |
| 3 | BRS | L3 | 7 | ("3253289" "4709435" "4710994" "4809421" "4831675" "5025522" "5617599").PN. | USPAT | 2004/10/14 11:35 | | | 0 |
| 4 | BRS | L4 | 4 | 5802652.URPN. | USPAT | 2004/10/14 11:35 | | | 0 |
| 5 | BRS | L5 | 10 | hwang.in. and girder | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB | 2004/10/14 11:36 | | | 0 |
| 6 | BRS | L6 | 1589 | 14/73,73.1,77.1,78.cc ls. 404/70.ccls. 248/188.2.ccls. | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB | 2004/10/14 12:02 | | | 0 |
| 7 | BRS | L7 | 74 | (14/73,73.1,77.1,78.c cls. 404/70.ccls. 248/188.2.ccls.) and deck and girder | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB | 2004/10/14 12:02 | | | 0 |